



Optional plug-in adapter

Part No. 01-1012

Includes: 1 ea. Molex plug with six Malco terminated, color-coded wires attached.
2 ea. Molex pins with Malco terminated, color-coded wire attached.
1 ea. .22 uf capacitor.

NOTES:

- a-J906 is P1006 in monitor receiver LFIFCN66.
- b-Out-1 is P1051 (S702) in monitor receiver.
- c-"DA" between audio filter input and output is cut out in monitor receiver.
- d-To insure proper operation, be sure antenna relay case is correctly grounded.
- e-Wire lengths shown are pin end to pin end.

SPECIAL NOTICE

WHEN MOUNTING THE TS-32 WITH A 90 DEGREE ANGLE BRACKET AGAINST THE PCB, BE SURE TO USE THE TWO FIBER SPACERS PROVIDED BETWEEN ANGLE BRACKET AND PCB. IF THIS IS NOT DONE, THE BRACKET WILL SHORT OUT FOILS ON THE PCB



Communications Specialists

426 W. Taft Ave., Orange, CA 92667
(714) 998-3021 (California) / (800) 854-0547