



NOTE: Remove jumper from Pin 4 of P401 to pin 6 of P402 and replace with 100K resistor.



Communications Specialists

426 W. Taft Ave., Orange, CA 92667
 (714) 998-3021 (California) / (800) 854-0547