



NOTE: Remove R133 (100K) on transmitter circuit board tone generator to disable internal tone generator.



Communications Specialists

426 W. Taft Ave., Orange, CA 92667
 (714) 998-3021 (California) / (800) 854-0547